

MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS - 1963 - A



AD

**AMMRC TR 84-16** 

# TIME-TEMPERATURE DEPENDENCE OF THE STRENGTH OF COMMERCIAL ZIRCONIA CERAMICS

LISELOTTE J. SCHIOLER, GEORGE D. QUINN and R. NATHAN KATZ

**April 1984** 



Prepared under Interagency Agreement DE-AE-101-77 CS51017

ARMY MATERIALS AND MECHANICS RESEARCH CENTER WATERTOWN, MASSACHUSETTS 02172

> This document has been approved for public release and sale; its distribution is unlimited.

# U.S. DEPARTMENT OF ENERGY

Office of Vehicle and Engine Research and Development Conservation and Renewable Energy




UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUME	READ INSTRUCTIONS BEFORE COMPLETING FORM				
I. REPORT NUMBER	2 GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER			
AMMRC TR 84-16	110 1146 2	k3			
4. TITLE (and Subtitle)	117.71.15	5 TYPE OF REPORT & PERIOD COVERED			
_ •	NOT OF THE OFFICER				
TIME-TEMPERATURE DEPENDE					
OF COMMERCIAL ZIRCONIA C	ERAMICS	5 PERFORMING ORG. REPORT NUMBER			
7. AUTHOR(#)		B. CONTRACT OR GRANT NUMBER(s)			
Liselotte J. Schioler, G	eorge D. Ouinn. and				
R. Nathan Katz	, , , , ,				
9. PERFORMING ORGANIZATION NAME		10 PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS			
Army Materials and Mecha		Interagency Agreement			
Watertown, Massachusetts	02172	DE-AE-101-77 CS51017			
DRXMR-MC		AMCMS Code: 69200R.8891			
11. CONTROLLING OFFICE NAME AND A		12. REPORT DATE			
U.S. Department of Energ		April 1984			
Office of Vehicle & Engi and Renewable Energy, Wa		13 NUMBER OF PAGES			
and kenewadie Energy, wa		11 15. SECURITY CLASS. (of this report)			
14. MONITORING AGENCY NAME & ADDR	(£ 25(1) different from Controlling Office)	13. SECURITY CERSS. (or this report)			
		Unclassified			
		15a. DECLASSIFICATION DOWNGRADING			
		SCHEDULE			
16. DISTRIBUTION STATEMENT (of this F	Report)				
Approved for public rele	ease; distribution unlimi	ted.			
17. DISTRIBUTION STATEMENT (of the a	batract entered in Block 20, if different fro	om Report)			
18 SUPPLEMENTARY NOTES Presented at the DoE Contractors' Meeting, Dearborn,					
		edings of the Twenty-First			
		pordination Meeting, Society			
of Automotive Engineers,	Inc., Warrendale, PA Ma	irch 1984.			
19 KEY WORDS (Continue on reverse side					
KET MOMOS (COULING ON SEVERSE SIDE	irnecessary and identity by Utoca number	<b>'</b>			
Zirconium oxides	Ceramic materials	İ			
Heat engines	High temperature				
Mechanical properties					
20 ABSTRACT (Continue on reverse side (	If necessary and Identify by block number)				
		İ			
		<b>,</b>			
	(SEE REVERSE SIDE)	j			
		ı			

## Block No. 20

# **ABSTRACT**

The unusual combination of attractive properties exhibited by transformation toughened zirconias (TTZ's) has focused attention on them as leading candidates for application in the adiabatic Diesel engine. These materials are age-hardened ceramic alloy systems and as such they are likely to be susceptible to overaging and loss of strength at long times at high temperatures. This paper presents preliminary data on the microstructural, phase and dimensional stability of aged TTZ's together with some data on the effects of aging on strength, toughness and modulus. Stress rupture data on TTZ's with both MgO and Y2O3 additions show a considerable decrease in load carrying ability at temperatures of 800°C and above.



# Time-Temperature Dependence of the Strength of Commercial Zirconia Ceramics

L. J. Schioler, G. D. Quinn, and R. N. Katz Army Materials and Mechanics Research Center Watertown, Massachusetts 02172

#### ABSTRACT

The unusual combination of attractive properties exhibited by transformation toughened zirconias (TTZ's) has focused attention on them as leading candidates for application in the adiabatic Diesel engine. These materials are age-hardened ceramic alloy systems and as such they are likely to be susceptible to overaging and loss of strength at long times at high temperatures. This paper presents preliminary data on the microstructural, phase and dimensional stability of aged TTZ's together with some data on the effects of aging on strength, toughness and modulus. Stress rupture data on TTZ's with both MgO and Y<sub>2</sub>O<sub>3</sub> additions show a considerable decrease in load carrying ability at temperatures of 800°C and above.

BECAUSE OF THEIR UNUSUAL combination of properties (E  $\sim$  steel, k  $\sim$  1/5 to 1/50 that of  $\rm Si_3N_4$  or SiC, an  $\alpha$ -steel, MOR  $\sim$  100 KSI, and a high  $\rm K_{1,C}\sim 10$ ), transformation toughened zirconias (TTZ) are leading candidates for cylinder liners, piston caps, head plates, valve seats, and other components for the adiabatic Diesel engine. These materials are age-hardened ceramic alloy systems and as such they are likely to be susceptible to overaging and loss of strength at long times at high temperatures (i.e. close to the age hardening temperatures). The possibility of overaging with its likely negative impact on materials performance was identified as a critical area of ignorance in the preliminary technology assessment on ceramics for Diesel engines previously prepared by AMMRC (1). Accordingly, a task was initiated to: a) define the extent and magnitude of the overaging (if any), and b) develop

toughened ceramic alloy systems which would not be susceptible to overaging at temperatures which may be encountered in advanced Diesels (1100-1200°C). Figure 1 gives an overview of the objective and approach of these two tasks. This paper will review progress on the task being carried out in-house at AMMRC. Professor Tien's paper later in this session (2) will review progress on the second task, being conducted at the University of Michigan.

#### TOUGHENED CERAMICS

#### SUBTASK I - AGING STUDIES OF TIZ

P.I.: L. SCHIOLER - AMMRC

OBJECTIVE: DEFINE EXTENT OF AGING PHENOMENA, IF ANY

APPROACH: PHASE I - EXPOSE COUPONS FOR VARIOUS 1-T AND EVALUATE CHANGES

IN: - PHASE CONTENT - DENSITY
- MICROSTRUCTURE - KIC
- DIMENSIONS - E

PHASE II - EVALUATE MOR AND FAILURE MODE AFTER EXPOSURE

#### SUBTASK II - TOUGHENED AI203 BASED CERAMICS

P.I.: PROF. TIEN - UNIVERSITY OF MICHIGAN

OBJECTIVE: DEVELOP OVERAGING RESISTANT ALLOY SYSTEMS (UP TO 1200°C)

APPROACH: SCREEN A1203/C1203 - Z102/M102 ALLOY SYSTEMS

SCREEN MULLITE - Z102/M102 ALLOY SYSTEMS

EVALUATE IN TWO PHASES AS IN SUBTASK I

#### Figure 1.

Zirconia ceramics of interest for Diesel engine application include transformation toughened zirconia (TTZ), partially stabilized zirconia (PSZ), and fully stabilized zirconia (FSZ). Figure 2 summarizes the main microstructural differences among these three types of zirconias and provides typical room temperature mechanical properties. The TTZ's are of major interest for application in highly stressed engine components due to their relatively high strength and

toughness. The high strength and toughness of TTZ is largely a result of the martensitic transformation of the metastable tetragonal phase to the stable monoclinic phase under stress. However, long time exposure to high temperatures may result in growth of the metastable tetragonal phase which in turn can trigger spontaneous transformation to the monoclinic phase, with the potential of signficant reductions in strength and toughness. Therefore, this paper will focus on our studies of the effect of aging on the physical and mechanical properties of TTZ's. Aging studies were carried out both with and without an applied load on the specimen. In the former case, density, phase content, microstructural stability, retained RT modulus of rupture (MOR), fracture toughness K<sub>IC</sub> and modulus of elasticity (More) we measured. In the latter case, stepped and modulus of elasticity (MOE) were temperature stress rupture (STSR) and supplemental stress rupture (SR) tests were conducted. From these studies it is possible to define the temperatures and stress levels below which TTZ's can be used without severe instability.

ZIRCONIA CERAMICS				
TRANSFORMATION TOUGHENED (TTZ's)	PARTIALLY STABILIZED WITH Y203, MgO, OR CaC     METASTABLE TETRAGONAL PHASE     OVERAGING BY TETRAG → MONO	MOR $\approx$ 500-600 MPa K <sub>1C</sub> $\approx$ 8-10 MN/m <sup>3/2</sup>		
PARTIALLY STABILIZED IPSZ's)	PARTIALLY STABILIZED WITH Y203, MgO, OR CaO     NO METASTABLE TETRAGONAL PHASE	MOR ≈ 300 MPa K <sub>IC</sub> ≈ 4 MN/m <sup>3/2</sup>		
FULLY STABILIZED	◆STABILIZED WITH Y203, MgO, OR CaO ◆ALL CUBIC PHASE	MOR $\approx$ 200-250 MPa $K_{IC} \approx 3$ MN/m <sup>3/2</sup>		

Figure 2.

#### MATERIALS

The materials studied were commerically available zirconias that were supplied free of charge by the manufacturers or Cummins Engine Company (material N only) on the condition that they be given code letters. Materials C, MN and N were optimally aged when received, while material F was not (the MOR and  $\rm K_{\rm LC}$  actually increased after heat treatment at 1000  $\rm C$  for 100 hours, but then decreased upon further heat treatment). The bend specimens were machined such that all samples had the same surface finish. This was done to minimize the effect of the surface transformation layer on comparison of the properties. As received properties of these four TTZ's are shown in Figure

,	AS-RECEIVED PROPERTIES OF COMMERCIAL ITZ				
CODE	ADDITIVE	DENSITY (g/cc)	RT MOR (MPa)	K <sub>IC</sub> (MN/m <sup>3/2</sup> )	RT MOE (GPa)
C	MgO	5.67	592	7.9	227
F	MgO	5.51	447	5.3	215
MN	MgO	5.65	520	10.2	199
N	Y2O3	5.75	778	-	198

Figure 3.

#### AGING STUDIES WITH NO APPLIED STRESS

Aging studies with no applied stress were carried out on the four TTZ's to evaluate microstructural and phase stability, dimensional stability, and potential changes in room temperature K<sub>IC</sub>, MOR and MOE after exposure to varying times at temperature. The results are presented below:

#### MICROSTRUCTURAL STABILITY

Changes in the coarse level microstructure of TTZ's with MgO additions are evident after only 50 hours of aging at 1300°C. However, after even 250 hours at 1000°C there is little evidence of microstructural change. (See Figure 4). The microstructures shown in Figure 4 are typical of material F, C and MN. By contrast, the TTZ with the Y<sub>2</sub>O<sub>2</sub> additive shows no evidence of microstructural change even after 250 hours at 1300° (See Figure 5). It should be noted that the fine level microstructure has not yet been examined and greater effects may be observed at the finer (i.e. 50-500Å) scale.

#### PHASE STABILITY

The phase stability of TTZ's was studied by measuring the changes in the percent of monoclinic phase as a function of both annealing temperature and time. The increase in the monoclinic phase is assumed to be the result of the spontaneous transformation of the metastable tetragonal phase, which provides the strength and toughness of the TTZ. Samples were annealed for 50, 100 and 250 hours for temperatures ranging between 900°C and 1300°C. Figure 6 shows the change in monoclinic phase with aging for two




Figure 4.

MgO containing TTZ's and an  $Y_2O_3$  containing TTZ. Both MgO containing TTZ's show similar behavior, namely the percent of monoclinic phase increases with time and temperature above  $900^{\circ}$ C. By contrast, the  $Y_2O_3$  containing TTZ shows a relatively negligible change in the amount of monoclinic phase until approximately  $1200^{\circ}$ C- $1300^{\circ}$ C. Even at  $1300^{\circ}$ C, the  $Y_2O_3$  containing TTZ has undergone less than half as much spontaneous transformation as the MgO containing materials.

## DIMENSIONAL STABILITY

Dimensional stability was evaluated by measuring the change in density with aging time and temperature and is shown in Figure 7. The change in density results from three separate effects: a) increase in crystal lattice volume as a result of the tetragonal to monoclinic transformation, b) increasing porosity at grain boundaries (See Figure 4) and c) the presence of an additional (as yet unidentified) phase at the grain boundaries. Since it has been shown above that the MgO containing TTZ's have both a greater amount of tetragonal to monoclinic phase change, and a greater amount of grain boundary porosity on aging, it is not suprising that they exhibit significantly greater volume change than Y203 containing material.




Figure 5.

### RETENTION OF MECHANICAL PROPERTIES

Figure 8 shows the effect of aging on the room temperature mechanical properties for one MgO containing TTZ. This result is typical of several MgO containing TTZ's examined. The MOR tests were carried out as described in Reference (3). The test samples were generally .110 X .080 X 2 inch, tested in 4 pt. flexure with spans of 0.6 X 1.2 inch. The K<sub>IC</sub> values were obtained by the indentation and fracture technique described by Lawn (4). MOE's were measured ultrasonically. It is significant that the retained RT mechanical properties all decrease with aging, with MOR showing the greatest change and MOE the least.

#### TIME-TEMPERATURE DEPENDANCE UNDER LOAD

Stepped Temperature Stress Rupture (STSR) testing (See Ref. 5) and limited supplemental standard stress rupture (SR) tests were carried out to obtain a preliminary evaluation of strength retention with time under load at various temperatures.

# STEPPED TEMPERATURE STRESS RUPTURE TESTS

As shown in Figure 9. The STSR results for all three MgO containing TTZ's were essentially similiar. In this figure, the numbers shown above each curve are the stress in MPa and the numbers under the curve are the temperatures in C.




Figure 6.




Figure 7.

EFFECT OF AGING ON PROPERTIES OF TTZ WITH MgO ADDITIONS				
	RT MOR (MPa)	K1C (MN/m <sup>3/2</sup> )	MOE (GPa)	
AS-RECEIVED	592	7.9	227	
AGED 100 hr @ 1000°C	395	6.5	213	
AGED 500 hr @ 1000°C	384	6.1	210	
CODE C MATERIAL				

Figure 8.

Each step on the curves represents a 24 hour interval. All samples were dead weight loaded in four point loading with 0.75 inch top and 1.50 inch bottom spans. Room temperature MOR's are shown to indicate the degree to which fracture strengths are reduced at elevated temperatures. No major evidence of static fatigue was encountered until 1200°C. However, in longer duration conventional stress-rupture testing, such behavior could well commence at lower temperatures. The failure mechanism for all of these MgO containing materials was via a creep fracture mode, with strains of 0.5 to 2.5%. In the case of material F the strains were large enough (up to~ 2.5%) so that the automatic shut off switch was tripped resulting in the premature test suspensions as shown on Figure 9. Creep strains of this magnitude resulted in the characteristic creep crack pattern shown in Figure 10.

In contrast, the STSR results for the Y<sub>2</sub>O<sub>3</sub> containing TTZ, Figure 11, indicated that static fatigue occurred at all temperatures at which testing was carried out (800-1100°C). The mechanism appeared to be slow crack growth for temperatures at or below 1000°C, and creep fracture for temperatures above 1100°C. Where creep fracture was the predominant failure mode, high strains (0.4-0.8% at 1100°C) were encountered. It is rather surprising that material N, which showed the greatest stability of microstructure, phase composition and aid density, showed the greatest reduction in load carring capability with time and temperature. This may be due to the fact that this material contains

0.72 wt. % Si (present as SiO<sub>2</sub>) which is believed to be present as a grain boundary glass (6,7). If the Si, and thus the glass, can be eliminated, then it is likely that Y<sub>2</sub>O<sub>3</sub> containing TTZ's should show performance equal or superior to the MgO containing materials.

#### SUPPLEMENTAL STRESS RUPTURE TESTS

Sufficient samples of materials C and MN were available to conduct supplemental conventional SR tests. In addition, more time was accumulated in a SR test of an early varient of material C (herein referred to as  $\mbox{C}^{\perp})$  which we reported on at last years Contractors Coordination Meeting (8). A summary of results from over 5200 hours of SR testing of eight tests bars is presented in Figure 12. Using this data, it was possible to estimate activation energies from creep in TTZ with MgO additives. (See Figure 13). Given the limited data available the activation energies of 75 Kcal/mole for material C and 100 Kcal/g mole for material MN are close enough that one can say they very likely share the same creep mechanism.

#### CONCLUSIONS

The conclusions of our studies to date indicate that:

- 1. All TTZ's investigated exhibit microstructural instabilities and degradation of strength at temperatures of 1000°C or less.
- Microstructural and other evidence indicates that MgO containing TTZ looses its strength as the result of an overaging process.
- 3. SR testing has demonstrated that MgO containing TTZ's can sustain stresses of 30 Ksi for hundreds to thousands of hours at 900°C with small strains.
- 4. One variety of Y<sub>2</sub>O<sub>3</sub> containing TTZ, which shows little microstructural evidence of aging, in fact has a greater time-temperature dependance of strength than the MgO containing TTZ's. Since this may be the consequence of a Si impurity (and resultant grain boundary glass), significant improvement of the high temperature mechanical properties of this material may be possible by elimination of the Si impurity.





Figure 9.

BESTERNAM CHARACTERS IN TRANSPORTED PROPERTY INS

TYPICAL PATTERN OF CREEP FRACTURE CRACKS ON TENSILE SURFACE OF MgO ADDITIVE TTZ



MATERIAL F, AFTER COMPLETION OF A STSR TEST INCLUDING THE FULL 24 HOURS AT  $1200^{\rm o}$ C. TOTAL STRAIN CALCULATED FROM SPECIMEN CURVATURE, WAS 2.5%

Figure 10.




Figure 11.

	STRESS-RUPTURE RESULTS OF TESTS ON MgO ADDITIVE TTZ'S				
<u> C00E</u>	STRESS (MPa)	TEMP.	TIME (hrs)	(%)	COMMENT
С	200	900	501 +	0.04	SAMPLE SURVIVED. TEST TERMINATED
	200	1000	511+	0.23	SAMPLE SURVIVED, TEST TERMINATED
	200	1100	125	1.03	SPECIMEN DEFORMED SUFFICIENT TO TRIP MICROSWITCH - NO FAILURE
ł	200	1200	26	0.96	FAILURE
MN	200	900	502	NEG.	SAMPLE SURVIVED, TEST TERMINATED
l	200	1000	502	0.58	SAMPLE SURVIVED, TEST TERMINATED
l	200	1100	13	1.62	FAILURE
c.	200	900	3020	0.20	SAMPLE SURVIVED, MOR IN FAST FRACT AT RT - 55% OF AVE. AS- RECEIVED, RT MOR

Figure 12.




Figure 13.

#### **ACKNOWLEDGMENT**

This work was supported by the Department of Energy under an interagency agreement with AMMRC (DOE 1A Noi DE-A101-77CS51017). The authors would also like to thank Drs. Brian Lawn and A. C. Gonzalez of the National Bureau of Standards for their assistance in obtaining the fracture toughness measurements.

#### REFERENCES

- Katz, R. N. and Lenoe, E. M., "Ceramics for Light Duty Diesel Engines: Preliminary Results a Technology Assessment", in the 19th Summary Report: Automotive Technology Development Contractors Coordination Meeting. DOE Report #CONF 811090 (October 1981) pp. 511 ff.
- Tien, T. Y. Presentation in this session
- Quinn, G. D., "Characterization of Turbine Ceramics After Long-Term Environmental Exposure", AMMRC TR-80-15, April 1980.
- Chantikul, P., Anstis, G. K., Lawn, B. R., and Marshall, D. B., Journal of American Ceramic Scoiety, 64 (1981) pp. 539-543
- Quinn, G. D. and Katz, R. N., American Ceramic Society Bulletin, <u>51</u> (1978), p.1057-1058
- Larsen, D. C. and Adams J. W., "Property Screening and Evaluation of Ceramic Turbine Materials" ITT Research Institute, Interim Technical Report #12, U.S. Air Force Contract #F33615-79-C-5100
- Heuer, A. H., "Microscopy Studies of Transformation Toughening" Presented at the New England Section of the American Ceramic Society Topical Meeting on Ceramic Composites, October 3-4 1983, Cape Code, MA
- 8. Katz, R. N. and Lenoe E. M., "Ceramic Technology Progess Report - DOE/AMMRC Ceramic Materials Program", SAE Publication P-120, April, 1983, Page 199 ff.

No. of No. of Copies Copies 12 Commander, Defense Technical Information Center, Cameron Station, Building 5, 5010 Duke Street, Alexandria, VA 22314 Commander, U.S. Air Force Wright Aeronautical Laboratories, Wright-Patterson Air Force Base, OH 45433 ATTN: AFWAL/MLLM, Dr. N. Tallan
AFWAL/MLLM, Dr. H. Graham
AFWAL/MLLM, Dr. R. Ruh
AFWAL/MLLM, Dr. A. Katz
AFWAL/MLLM, Dr. A. Katz
AFWAL/MLLM, Mr. K. S. Mazdiyasni
Aero Propulsion Labs, Mr. R. Marsh National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161 Director, Defense Advanced Research Projects Agency, 1400 Wilson Boulevard, Arlington, VA 22209 National Aeronautics and Space Administration, Washington, DC 20546 ATTN: Mr. C. Bush AFSS-AD, Office of Scientific and Technical Information ATTN: Dr. B. Wilcox Haj S. Wax Dr. W. Snowdor Battelle Columbus Laboratories, Metals and Ceramics ATTN: Mr. Winston Duckworth
Dr. D. Niesz Mational Aeronautics and Space Administration, Lewis Research Center, 21000 Brookpark Road, Cleveland, OH 44135 ATTN: J. Accurio, USAMRDL Dr. H. B. Probst, MS 49-1 Mr. S. Dutta ī Dr. R. Wills Deputy Chief of Staff, Research, Development, and Acquisition, Headquarters. Department of the Army, Washington, DC 20301 ATTN: DAMA-PPP, Mr. R. Vawter National Aeronautics and Space Administration, Langley Research Center, Hampton, VA 23665 1 ATTN: Mr. J. Buckley, Mail Stop 387 Commander, Army Research Office, P.O. Box 12211, Research Triangle Park, NC 27709 ATTN: Information Processing Office Dr. G. Mayer Dr. P. Parrish Department of Energy, Division of Transportation 20 Massachusetts Avenue, N.W., Washington, DC 20545 1 ATTN: Mr. Robert Schultz (TEC) Commander, U.S. Army Missile Command, Redstone Arsenal, AL 35898 Department of Transportation, 400 Seventh Street, S.W., Washington, DC 20590 1 ATTN: Mr. M. Lauriente ATTN: Technical Library
DRSMI-TB, Redstone Scientific Information Center National Bureau of Standards, Hashington, DC 20234 U.S. Army Aviation Research and Development Command, 4300 Goodfellow Boulevard, St. Louis, MO 63120 ATTN: DROAV-EGX 1 ATTN: Dr. S. Wiederhorn DRDAY - OE National Research Council, National Materials Advisory Board, 2101 Constitution Avenue, Washington, DC 20418 Technical Library ATTN: D. Groves R. M. Spriggs Commander, U.S. Army Tank-Automotive Command, Warren, MI 48090 Commande... Warren, MI 48090 ATIN: Or. W. Bryzik Mr. W. Wheelock O. Rose Admiralty Materials Technology Establishment, Polle, Dorset BHI6 6JU, UK ATTN: Dr. D. Godfrey Dr. M. Lindley DRSTA-UL, Technical Library AiResearch Manufacturing Company, AiResearch Casting Company, 2525 West 190th Street, Torrance, CA 90505 1 ATTN: Mr. K. Styhr Commander, U.S. Army Armament Materiel Readiness Command, Rock Island, It. 61299AiResearch Manufacturing Company, Materials Engineering Dept., 111 South 34th Street, P.O. Box 5217, Phoenix, AZ 35010 ATTN: Mr. D. W. Richerson, MS 93-393/503-44 ATTN: Technical Library Commander, U.S. Army Mobility Equipment Research and Development Command, Fort Belvoir, VA 22060 1 ATT%: DROME-EM, Mr. P. Arnold AVCO Corporation, Applied Technology Division, Lowell Industrial Park, Lowell, MA 01887 1 ATTN: Dr. T. Vasilos Commander, U.S. Army Foreign Science and Technology Center, 2007 7th Street, N.E., Charlottesville, VA 22901 ATTN: Military Tech, Mr. S. Mingledorf Carborundum Company, Research and Development Division, P.O. Box 1054, Niagara Falls, NY 14302 1 ATTN: Dr. J. A. Coppola Director, Eustis Directorate, U.S. Army Mobility Research and Development Laboratory, Fort Eustis, VA 23604 ATTV: Mr. J. Robinson, DAVDL-E-MOS (AVRADCOM) Mr. J. Lane Case Western Reserve University, Department of Metallurgy, Cleveland,  $\,$  OH  $\,$  44106  $\,$ 1 ATTN: Prof. A. H. Heuer Chief of Naval Research, Arlington, VA 22217 ATTN: Gode 471 Or. A. Diness Or. R. Pohanka Cummins Engine Company, Columbus, IN 47201 ATTN: Mr. R. Kamo Dr. J. Patton Electric Power Research Institute, P.O. Box 10412, 3412 Hillview Avenue, Palo Alto, CA 94304 1 ATTN: Dr. A. Cohn Naval Research Laboratory, Washington, DC 20375 ATTN: Mr. P. Rice Headquarters, Naval Air Systems Command, Washington, DC 20360 ATTN: Code 5203 Code MAT-042M Mr. I. Macklin European Research Office, 223 Old Maryleborne Road, London, NW1 - 5the, England ATTN: Dr. F. Roth LT COL James Kennedy mander, U.S. Air Force of Scientific Research, Iding 410, Bolling Air Force Base, Washington, DC 20332 No. 5r. 5. Winich

KOSSODO GEOGRADA PEDIDIDADA RESSESSAS RECEGERANTA

No. o		No. Copi	
Copie		COPI	
	Ford Motor Company, Turbine Research Department,		Norton Company, Worcester, MA 01606
	20000 Rotunda Drive, Dearborn, MI 48121		ATTN: Dr. N. Ault
1	ATTN: Mr. A. F. McLean	1	Dr. M. L. Torti
1	Mr. A. Ezis		
1	Mr. J. A. Mangels		Pennsylvania State University, Materials Research Laboratory,
1	Dr. R. Govila		Materials Science Department, University Park, PA 16802
1	Mr. R. Baker	1	ATTN: rof. R. E. Tressler
		1	Prof. V. S. Stubican
	General Electric Company, Research and Development Center,		
	Box 8, Schenectady, NY 12345		RIAS, Division of the Martin Company, Baltimore, MD 21203
	ATTN: Dr. R. J. Charles	1	ATTN: Dr. A. R. C. Westwood
ī	Dr. C. D. Greskovich		
ī	Dr. S. Prochazka		Stanford Research International, 333 Ravenswood Avenue,
•	Dr. St. Freendand		Menlo Park, CA 94025
	Georgia Institute of Technology, EES, Atlanta, GA 30332	1	ATTN: Dr. P. Jorgensen
	ATTN: Mr. J. D. Walton	i	Dr. D. Rowcliffe
•	ATTAL PIEL OF MOTION	•	DI. D. ROMETTITE
	GTE Laboratories, Waltham Research Center, 40 Sylvan Road, Waltham		State University of New York at Stony Brook, Department
	MA 02154	•	
,		,	of Materials Science, Long Island, NY 11790
	ATTN: Dr. C. Quackenbush	1	ATTN: Prof. Franklin F. Y. Wang
1	Dr. W. H. Rhodes		
			United Technologies Research Center, East Hartford, CT 06108
_	IIT Research Institute, 10 West 35th Street, Chicago, IL 60616		ATTN: Dr. J. Brennan
1	ATTN: Mr. S. Bortz, Director, Ceramics Research	1	Dr. F. Galasso
	Institut fur Werkstoff-Forschung, DFVLR, 505 Porz-Wahn, Linder		University of California, Lawrence Livermore Laboratory,
_	Hohe, Germany		P. O. Box 808, Livermore, CA 94550
1	ATTN: Dr. W. Bunk	1	ATTN: Dr. C. F. Cline
	International Harvester, Solar Division, 2200 Pacific Highway,		University of Florida, Department of Materials Science and Engineering,
	P.O. Box 80966, San Diego, CA 92138		Gainesville, FL 32601
1	ATTN: Dr. A. Metcalfe	1	ATTN: Dr. L. Hench
	Kawecki Berylco Industries, Inc., P.O. Box 1462,		University of Newcastle Upon Tyne, Department of Metallurgy and
	Reading, PA 19603		Engineering Materials, Newcastle Upon Tyne, NEI 7 RU, England
1	ATTN: Mr. R. J. Longnecker	1	ATTN: Prof. K. H. Jack
	Martin Marietta Laboratories, 1450 South Rolling Road, Baltimore,		University of Washington, Ceramic Engineering Division, FB-10.
	MD 21227		Seattle, WA 98195
1	ATTN: Dr. J. Venables	1	ATTN: Prof. James I. Mueller
		1	Prof. R. Bradt
	Massachusetts Institute of Technology, Department of Metallurgy		
	and Materials Science, Cambridge, MA 02139		Westinghouse Electric Corporation, Research Laboratories,
1	ATTN: Prof. R. L. Coble		Pittsburgh, PA 15235
1	Prof. H. K. Bowen	1	ATTN: Dr. R. J. Bratton
ī	Prof. W. D. Kingery		
-	· · · · · · · · · · · · · · · · · · ·		Director, Army Materials and Mechanics Research Center,
	Midwest Research Institute, 425 Volker Boulevard,		Watertown, MA 02172
	Kansas City, MO 64110	2	ATTN: DRXMR-PL
1	ATTN: Mr. Gordon W. Gross, Head, Physics Station	3	Authors
•	min in a worden we dieday inches ingales acceren	•	7,000,00

Kasa needog baasas popping produce produce needog needog passas passas produces produces produces produces prod

THE PROPERTY OF THE PROPERTY O

STRENGTH OF COMMERCIAL ZIRCONIA CERAMICS Materials and Mechanics Research Center, Liselotte J. Schioler, George D. Quinn, Watertown, Massachusetts 02172 TIME-TEMPERATURE DEPENDENCE OF THE and R. Nathan Katz ATTA

UNCLASSIFIED
UNLIMITED DISTRIBUTION

ð

Technical Report AWMRC TR 84-16, April 1984, 11 pp - illus, Interagency Agreement DE-AE-101-77 CS51017, AMCHS Code 69200R.8891

Mechanical properties

Zirconjum oxides **Key Words** 

Heat engines

application in the adiabatic Diesel engine. These materials are age-hardened ceramic alloy systems and as such they are likely to be susceptible to overaging and loss of strength at long times at high temperatures. This paper presents preliminary data on the microstructural, phase and dimensional stability of aged TIZ's strengther with some data on the effects of aging on strength, toughness and modulus. Stress rupture data on TIZ's with both MgO and Y203 additions show a considerable decrease in load carrying ability at temperatures of 800°C and above. unusual combination of attractive properties exhibited by transformation tough-<u>8</u>

Materials and Mechanics Research Center, μ¥

Watertown, Massachusetts 02172 TIME-TEMPERATURE DEPENDENCE OF THE STRENGTH OF COMMERCIAL ZIRCONIA CERAMICS Liselotte J. Schioler, George D. Quinn, and R. Nathan Katz

Technical Report AWMRC TR 84-16, April 1984, 11 pp -111us, Interagency Agreement DE-AE-101-77 CS51017, AMCMS Code 69200R.8891

Heat engines Mechanical properties

Zirconium oxides

Key Words

ened 27rconias (TT2's) has focused attention on them as leading candidates for application in the adiabatic Diesel engine. These materials are age-hardened ceramic alloy systems and as such they are likely to be susceptible to overaging and loss of strength at long times at high temperatures. This paper presents pre-liminary data on the microstructural, phase and dimensional stability of aged TT2's together with some data on the effects of aging on strength, toughness and modulus. Stress rupture data on TT2's with both M90 and Y203 additions show a considerable decrease in load carrying ability at temperatures of 800°C and above. unusual combination of attractive properties exhibited by transformation tough

STRENGTH OF COMMERCIAL ZIRCONIA CERAMICS Liselotte J. Schioler, George D. Quinn, Materials and Mechanics Research Center, Watertown, Massachusetts 02172 TIME-TEMPERATURE DEPENDENCE OF THE and R. Nathan Katz Army

UNCLASSIFIED UNLIMITED DISTRIBUTION

Ş

Technical Report AWMRC TR 84-16, April 1984, 11 pp - illus, interagency Agreement DE-AE-101-77 CS51017, AMCMS Code 69200R.8891

Heat engines Mechanical properties

Zirconium oxides

**Key Words** 

The unusual combination of attractive properties exhibited by transformation toughened zirconias (TIZ's) has focused attention on them as leading candidates for application in the adiabatic Diesel engine. These materials are age-hardened ceramic alloy systems and as such they are likely to be susceptible to overaging and loss of strength at long times at high temperatures. This paper presents preliminary data on the microstructural, phase and dimensional stability of aged TIZ's together with some data on the effects of aging on strength, toughness and modulus. Stress rupture data on TIZ's with both MgO and Y203 additions show a considerable decrease in load carrying ability at temperatures of 800°C and above.

Watertown, Massachusetts 02172 TIME-TEMPERATURE DEPENDENCE OF THE STRENGTH OF CUMMERCIAL ZIRCONIA CERMICS Liselotte J. Schioler, George D. Quinn, Materials and Mechanics Research Center, Aray

UNCLASSIFIED
UNLIMITED DISTRIBUTION

fechnical Report AWMRC TR 84-16, April 1984, 11 pp illus, Interagency Agreement DE-AE-101-77 CS51017,
AMCMS Code 69200R.8891 and R. Nathan Katz

Zirconium oxides **Key Words** 

UNCLASSIFIED
UNLIMITED DISTRIBUTION

8

Heat engines Mechanical properties

The unusual combination of attractive properties exhibited by transformation toughened zirconias (TTZ's) has focused attention on them as leading candidates for application in the adiabatic Diesel engine. These materials are age-hardened ceramic alloy systems and as such they are likely to be susceptible to overaging and loss of strength at long times at high temperatures. This paper presents preliminary data on the microstructural, phase and dimensional stability of aged TTZ's together with some data on the effects of aging on strength, toughness and modulus. Stress rupture data on TTZ's with both MgO and Y2O3 additions show a considerable decrease in load carrying ability at temperatures of 800°C and above.